

2018 Yankton County Bridge Inspections County Road Structures

Presented by:
Kevin Goff, PE
Adam Polley, PE
Joshua Prather, EI

CLARK
ENGINEERING

Inspection Overview

- 40 bridges on county roads (this includes the 4 James River Bridges)
- Sufficiency Ratings:
 - 100 – 60 (Good Condition) – 31 bridges (78%)
 - 60-40 (Fair Condition) – 7 bridge (17%)
 - < 40 (Poor Condition) – 2 bridges (5%)
- Posted Structures
 - 19 Posted Structures
 - 21 Legal Load Structures

CLARK
ENGINEERING

68-070-158

- 36.0' Single Span Steel Girder
- Built in 1940
- 2.8 miles south of Utica, SD
- Sufficiency Rating = 30.6
- Structure is nearing the end of its useful life and should be programmed for replacement.

CLARK
ENGINEERING

68-070-158



Profile Facing West



Alignment Facing South

CLARK
ENGINEERING

68-070-158



Typical Wide Vertical
Crack on Backwalls



Typical Map Cracking with
Efflorescence on Underside of Deck

CLARK
ENGINEERING

68-070-158



Typical Minor Section Loss
Top Flange of Girders



Weight Limit Sign

CLARK
ENGINEERING

68-070-158

Repair Recommendations:

- Structure is nearing the end of its useful life and should be programmed for replacement.
- Upgrade the bridge railing to meet current standards.
- Install approach guardrail on each approach.
- Open the deck drains.
- Continue to post the structure at Single Unit: 17 Tons, Combinations: 29 Tons.

CLARK
ENGINEERING

68-137-088

- 39.0' Single Span Steel Girder
- Built in 1930
- 2.8 miles south and 10.3 miles west of Irene, SD
- Sufficiency Rating = 43.3

CLARK
ENGINEERING

68-137-088



Profile Facing West



Alignment Facing South

CLARK
ENGINEERING

68-137-088



Typical Underside of the Deck and the Girders



Jacket on Abutment 1

CLARK
ENGINEERING

68-137-088



Jacket on Abutment 2



Weight Limit Sign

CLARK
ENGINEERING

68-137-088

Repair Recommendations:

- Upgrade the bridge railing to meet current standards.
- Replace the Type 3 object markers with Type 2 object markers.
- Continue to post the structure at Single Unit: 11 Tons, Combinations: 18 Tons.

CLARK
ENGINEERING

68-180-133

- 53.6' Three Span Reinforced Concrete Slab
- Built in 1941
- 1.7 miles north and 5.0 miles west of Volin, SD
- Sufficiency Rating = 45.8
- Structure is nearing the end of its useful life and should be programmed for replacement.

CLARK
ENGINEERING

68-180-133



Profile Facing East



Alignment Facing North

CLARK
ENGINEERING

68-180-133



Heavy Efflorescence and Stalactites
at the East end of Span 1
(Typical to the West End)



Abutment 1

CLARK
ENGINEERING

68-180-133



Heavy Efflorescence on the East End of Bent 2 (Typical to the West End of Bent 2)



Weight Limit Sign

CLARK
ENGINEERING

68-180-133

Repair Recommendations:

- Structure is nearing the end of its useful life and should be programmed for replacement.
- Install approach guardrail with appropriate signing.
- Upgrade the bridge railing to meet current standards.
- Continue to post the structure at Single Unit: 18 Tons, Combinations: 30 Tons.

CLARK
ENGINEERING

68-140-015

- 31.0' Single Span Steel Girder
- Built in 1930
- 4.5 miles north and 10.0 miles west of Irene, SD
- Sufficiency Rating = 47.0
- This structure is nearing the end of its useful life and should be programmed for replacement.

CLARK
ENGINEERING

68-140-015



Profile Facing East



Alignment Facing North

CLARK
ENGINEERING

68-140-015



General Layout of the Underside of the Deck and Girders



North Backwall

CLARK
ENGINEERING

68-140-015



South Backwall



Weight Limit Sign

CLARK
ENGINEERING

68-140-015

Repair Recommendations:

- This structure is nearing the end of its useful life and should be programmed for replacement.
- Upgrade the bridge railing to meet current standards.
- Continue to post the structure at Single Unit: 20 Tons, Combinations: 33 Tons.



68-043-023

- 40.5' Single Span Prestressed Concrete Double Tee
- Built in 1975
- 6.7 miles north and 2.3 miles east of Lesterville, SD
- Sufficiency Rating = 55.8



68-043-023



Profile Facing South



Alignment Facing East



68-043-023



Spall on the North Leg of Unit 7
over Abutment 1



Typical Deterioration of Piles
at the Ground line

CLARK
ENGINEERING

68-043-023



Undermining at the North End of the East Backwall

CLARK
ENGINEERING

68-043-023

Repair Recommendations:

- Replace the timber abutments.
- Repair undermining at Abutment 2 and riprap.
- Post the structure at Single Unit: 18 Tons, Combinations: 30 Tons (75% of Legal Loads) due to the condition of the piles.

CLARK
ENGINEERING

68-024-008

- 29.1' Two Span Steel Girder
- Built in 1950 / 1997
- 8.2 miles north and 0.4 miles east of Lesterville, SD
- Sufficiency Rating = 56.3
- This structure is nearing the end of its useful life and should be programmed for replacement.

CLARK
ENGINEERING

68-024-008



Profile Facing North



Alignment Facing West

CLARK
ENGINEERING

68-024-008



General Layout of Underside of Deck and Girders



Damage to West End of Deck

CLARK
ENGINEERING

68-024-008



Weight Limit Sign

CLARK
ENGINEERING

68-024-008

Repair Recommendations:

- Complete replacement of this structure in 2019.

CLARK
ENGINEERING

68-200-016

- 36.5' Single Span Steel Girder
- Built in 1940
- 1.6 miles south of Center Point, SD
- Sufficiency Rating = 57.1

CLARK
ENGINEERING

68-200-016



Profile Facing West



Alignment Facing North

CLARK
ENGINEERING

68-200-016



General Layout of the Underside of the Deck and Girders



Weight Limit Sign

CLARK
ENGINEERING

68-200-016

Repair Recommendations:

- Upgrade the bridge railing to meet current standards.
- Arrest scour at southeast corner under the structure with riprap.
- Post the structure at Single Unit: 21 Tons, Combinations: 36 Tons.

CLARK
ENGINEERING

68-209-030

- 31.0' Single Span Steel Girder
- Built in 1940
- 3.0 miles north and 3.1 miles west of Irene, SD
- Sufficiency Rating = 60.0

CLARK
ENGINEERING

68-209-030



Profile Facing South



Alignment Facing East

CLARK
ENGINEERING

68-209-030



General Layout of the Underside of the Deck and Girders



Concrete Deterioration at the North End of the East Backwall

CLARK
ENGINEERING

68-209-030



Weight Limit Sign

CLARK
ENGINEERING

68-209-030

Repair Recommendations:

- Upgrade the bridge railing to meet current standards.
- Continue to post the structure at Single Unit: 20 Tons, Combinations: 34 Tons.

CLARK
ENGINEERING

68-230-159

- 50.0' Single Span Prestressed Concrete Double Tee
- Built in 1974
- 1.0 mile south of Volin, SD
- Sufficiency Rating = 61.2

CLARK
ENGINEERING

68-230-159



Profile Facing East



Alignment Facing North

CLARK
ENGINEERING

68-230-159



Pile 1 of Abutment 1



Pile 3 of Abutment 1

CLARK
ENGINEERING

68-230-159



Undermining at the East End
of the South Backwall



Weight Limit Sign

CLARK
ENGINEERING

68-230-159

Repair Recommendations:

- Install concrete diaphragms at the abutments and at midspan.
- Replace both timber abutments with concrete abutments.
- Install approach guardrail with appropriate signing at the northeast and southwest approaches.
- Repair damaged and loose guardrail supports
- Repair undermining of Abutment 1.
- Continue to post the structure at Single Unit: 21 Tons, Combinations: 36 Tons.

CLARK
ENGINEERING

68-050-159

- 26.0' Single Span Steel Girder
- Built in 1940
- 2.8 miles south and 2.0 miles west of Utica, SD
- Sufficiency Rating = 65.5

CLARK
ENGINEERING

68-050-159



Profile Facing East



Alignment Facing North

CLARK
ENGINEERING

68-050-159



General Condition of Underside of Deck and Girders



Weight Limit Sign

CLARK
ENGINEERING

68-050-159

Repair Recommendations:

- This structure is nearing the end of its useful life and should be programmed for replacement.
- Upgrade the bridge railing to meet current standards.
- Install approach guardrail on each approach.
- Continue to post the structure at Single Unit: 19 Tons, Combinations: 32 Tons.

CLARK
ENGINEERING

68-070-113

- 140.0' Five Span Reinforced Concrete Slab
- Built in 1956
- 1.7 miles north of Utica, SD
- Sufficiency Rating = 68.5

CLARK
ENGINEERING

68-070-113



Profile Facing East



Alignment Facing South

CLARK
ENGINEERING

68-070-113



Exposed Rebar in Southeast Corner
and Typical Scaling of Deck



Weight Limit Sign

CLARK
ENGINEERING

68-070-113

Repair Recommendations:

- Consider installing a polymer chip seal.
- Install approach guardrail with appropriate signing.
- Upgrade the bridge railing to meet current standards.
- Remove the trees growing under the structure.
- Continue to post the structure at Single Unit: 21 Tons, Combinations: 36 Tons.

CLARK
ENGINEERING

68-019-015

- 36.4' Single Span Steel Girder
- Built in 1938
- 7.5 miles north and 0.1 miles west of Lesterville, SD
- Sufficiency Rating = 71.0



68-019-015



Profile Facing North



Alignment Facing West



68-019-015



General Layout of Underside of Deck and Girders



Concrete Deterioration in North Exterior Bay



68-019-015



Typical Efflorescence and Stalactites on the underside of the Deck



Typical Section Loss on Top Flanges of Girders

CLARK
ENGINEERING

68-019-015



Cracking and Deterioration on North End of East Backwall



Weight Limit Sign

CLARK
ENGINEERING

68-019-015

Repair Recommendations:

- Upgrade the bridge railing to meet current standards.
- Move fence back to ROW on north side of structure.
- Continue to post the structure at Single Unit: 19 Tons, Combinations: 32 Tons.

CLARK
ENGINEERING

68-043-014

- 81.8' Two Span Steel Girder
- Built in 1940
- 7.6 miles north and 2.3 miles east of Lesterville, SD
- Sufficiency Rating = 73.2



68-043-014



Profile Facing North



Alignment Facing West



68-043-014



Concrete Deterioration with Exposed Rebar on the South Edge of the Deck over Bent 2



Typical Section Loss on the Bottom Flange of Girders 2-9 at Abutment 1



68-043-014



Concrete Deterioration at
the South End of Bent Cap 2



Weight Limit Sign

CLARK
ENGINEERING

68-043-014

Repair Recommendations:

- This structure is programmed for replacement in 2020.
- Upgrade the bridge railing to meet current standards.
- Remove the tree debris at Bent 2.
- Continue to post the structure at Single Unit: 19 Tons,
Combinations: 32 Tons.

CLARK
ENGINEERING

68-061-022

- 31.6' Single Span Steel Girder
- Built in 1935
- 10.8 miles north and 0.8 miles west of Utica, SD
- Sufficiency Rating = 75.2

CLARK
ENGINEERING

68-061-022



Profile Facing South



Alignment Facing West

CLARK
ENGINEERING

68-061-022



General Layout of the Underside of the Deck and the Girders



Cracking on the South End of the West Backwall

CLARK
ENGINEERING

68-061-022



Weight Limit Sign

CLARK
ENGINEERING

68-061-022

Repair Recommendations:

- This structure is nearing the end of its useful life and should be programmed for replacement.
- Upgrade the bridge railing to meet current standards.
- Monitor the bowing of the girders.
- Continue to post the structure at Single Unit: 20 Tons, Combinations: 34 Tons.



68-050-105

- 128.8' Five Span Reinforced Concrete Slab
- Built in 1963
- 2.0 miles west and 2.5 miles north of Utica, SD
- Sufficiency Rating = 89.1



68-050-105



Profile Facing West



Alignment Facing South



68-050-105



Poor Consolidation of
Column 1 Bent 4



Weight Limit Sign

CLARK
ENGINEERING

68-050-105

Repair Recommendations:

- Patch areas of poor consolidation on the columns.
- Upgrade the bridge railing to meet current standards.
- Remove the trees from under the structure.
- Continue to post the structure at Single Unit: 21 Tons, Combinations: 36 Tons.

CLARK
ENGINEERING

68-200-103

- 93.0' Three Span Reinforced Concrete Slab
- Built in 1996
- 3.0 miles west and 4.5 miles north of Volin, SD
- Sufficiency Rating = 99.9

CLARK
ENGINEERING

68-200-103



Profile Facing West



Alignment Facing South

CLARK
ENGINEERING

68-200-103

Repair Recommendations:

- Consider installing an epoxy deal seal.

CLARK
ENGINEERING

Questions?



CLARK
ENGINEERING

Thank you for your time!

Presented by:
Kevin Goff, PE
Adam Polley, PE
Joshua Prather, EI

CLARK
ENGINEERING
